

Change List for Win10 Driver 10.0.0.318 to 10.0.0.321

Update 6/30/2015

Qualcomm Atheros is continuing Hot Fixes. This will be a list of running changes as we continue to fix defects against Win8.1 10.0.0.x base code.

Software changes between build 10.0.0.315 and 10.0.0.318 (Win10 SID: 1726434)

- 1) [EV14468][SF01965708][NFA222] BSOD (0xE1) happens during the stress tests on Win8.1 (CL#1288522/CL#1296401)
- 2) [EV143863][Win8.1] BT CPT fail(throughput < 0.15 Mbps) (CL#1296861)
- 3) [NOEV] CPT failure with NFA335 on S41-35 (Cl#1298474)
- 4) [EV144569][WB222][WLAN][Win10][HLK]Wi-Fi Direct Basic Reconnect Tests - Functional test fail (CL#1303844)

Software changes between build 10.0.0.318 and 10.0.0.321 (Win10 SID: 1736336)

- 1) [EV144867] [NFA335/NFA222] Support to read regulatory information from SMBIOS
- 2) [NFA335] 0xD1 BSOD when running S3 stress test