

# E-GATE DRIVER RELEASE NOTE

## VERSION 2.6.0.0

---

---

## 1. ENVIRONMENT

### 1.1 OPERATING SYSTEM

This version of the e-gate USB 2.6.0.0 drivers were tested on the following platforms.

- Windows 2000 Professional, SP0 - SP4
- Windows XP Professional, Windows XP Professional SP1, Windows XP Professional SP2
- Windows Server 2003 Standard Edition.
- Windows 98 / 98SE
- Windows Me

### 1.2 SOFTWARE

Windows 2000/XP/Server 2003

No specific software prerequisites are required.

Windows 98/98SE/ME

The **Microsoft Smart Card Base Components** must be installed on the computer for the smart card readers to function properly. The *Microsoft Smart Card Base Components* are available from the Reflex Readers Downloads website, [www.reflexreaders.com/Support/Downloads/downloads.html](http://www.reflexreaders.com/Support/Downloads/downloads.html).

### 1.3 HARDWARE

x86 PC compatible computer with USB 1.1 / 2.0 Host controller.

The e-gate technology embeds the USB interface electronics normally found in a smart card reader within the card itself. Therefore, an e-gate USB Smart Card does not require a smart card reader. The e-gate USB Smart Card simply plugs into a USB port on the computer using one of these two connector types:

- A token form factor connector if the card is used in its cut-down token format.
- A desktop form factor connector if the card is used in standard smart card format.

## 2. INSTALLATION

See the installation notes in the PDF file of the operating system target distribution package.

## **E-GATE DRIVER RELEASE NOTE VERSION 2.6.0.0**

---

### **3. HISTORY OF CHANGES**

#### **3.1 NEW FUNCTIONNALITIES**

Compared to version 2.4.0.0, the version 2.6.0.0 supports the following new functionalities.

##### **New supported e-gate smart cards :**

- ✓ Cyberflex Access e-gate 64K V2B (SmartXA) with FIPS (Federal Information Processing Standards).

##### **New supported operating system :**

- ✓ Windows Server 2003
- ✓ Windows 98.

#### **3.2 FIXES.**

The version 2.6.0.0 of the driver implements the following fixes from 2.4.0.0

##### **Windows 98/98SE/ME driver installation**

- ✓ Sometimes, exiting setup generated a trap, but the installation was successful.
- ✓ Message box has been added in order to warn the user that a reboot is required.

##### **Windows XP/2000**

- ✓ The power management setting is properly managed and properly displayed in the Device Manager e-gate tab.
- ✓ In the Device Manager, if more than 1 card is available, the displayed versions of the drivers are always consistent after the installation of the version 2.6.0.0
- ✓ Centrino Compliance